



Preliminary Information

PIT5849D Tail Lights Remain On After Passive Locking and/or Dead Battery

Product Investigation Review Required

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Silverado 1500 LTD	2022	All	All	All	All
Chevrolet	Silverado 2500HD/3500HD	2022	All	All	All	All
GMC	Sierra 1500 Limited	2022	All	All	All	All
GMC	Sierra 2500HD/3500HD	2022	All	All	All	All

Involved Region or Country	North America
Condition	Some customers may comment that the rear tail / parking lights stay on and do not time out after exiting the vehicle and passive locking the vehicle. This condition can lead to a dead battery.
Cause	The cause of this condition is a BCM calibration issue.

Correction:

To correct this concern perform Customer Satisfaction Program [N212344990](#) "Turn Signals Remain On After Passive Door Locking".

In some rare cases, a vehicle may have the same symptoms as listed in [N212344990](#), but the vehicle is not involved in the customer satisfaction program. If the BCM has the latest calibration and still exhibits the concern, then GM Engineering is working on a fix. Because this condition only occurs if passive locking is used please turn off passive locking in vehicle settings until a fix is released. Also, Please submit a Field Product Report (FPR) following bulletin [02-00-89-002T](#).

Additional SI Keywords

Park left right lamps lamp lighting light taillight taillamp

Version History

Version	5
Modified	07/26/2021 - Created on. 09/23/2021 - Updated to remove the light duty trucks. 10/28/2021 - Updated the correction 11/29/2021 - Updated the correction. 11/30/2021 - Update the model list to include light duty trucks



GENERAL MOTORS

© 2021 General Motors. All Rights Reserved.