

SERVICE BULLETIN 590 - ENGINE COVER BOLT TORQUE



Notice Information

Ref	19795
Posted Date:	
Posted To:	General Manager / Business Owner, Technician, Parts / Accessories Coordinator, Sales Executive, Clothing Sales, Sales Manager, Aftersales Manager, Service Leader / Advisor, Accounts / Admin, Marketing Executive
Subject:	Service/Technical

TOL NOTICE (US&CA) – October 18, 2021**TOL Ref. #19795-SVC****SERVICE BULLETIN 590 – RE-TORQUE ENGINE COVER BOLTS**

Triumph has released Service Bulletin 590. Internal investigations have identified the alternator, clutch, crank & balance cover fixings must be re-torqued as described in the procedure outlined in the bulletin.

SB 590: Re-Torque Engine Cover Bolts				
Bulletin #	Models Affected	VIN Range		Markets
590	Speed Triple 1200 RS	From AD2117	To AW0999	All Markets

Some affected motorcycles listed in the VIN range will have been modified and repaired by Triumph prior to their release from the factory. Unmodified motorcycles can be identified by checking the 'VIN Enquiry' on www.triumphonline.net. **Motorcycles in the affected VIN range must be modified prior to delivery to the customer, or at the next dealership visit.**

Consult **Triumph Online (TOL) / Service Bulletin Page** (Bulletin # 590) or the attached [Service Bulletin 590](#) PDF for additional information including Fitting, Warranty Claim and Part Ordering instructions if applicable. Please also ensure that all relevant staff are up to date on these service instructions.

Reminder: Use the “VIN Enquiry” function within TOL (found under the **Service / Technical** drop-down menu) to search for any outstanding bulletins or recalls whenever a new motorcycle arrives, or a Triumph owner visits your dealership.

If you have any additional questions, please contact Triumph Customer Support at (888) 284-6288.