

SERVICE BULLETIN 591 - EXHAUST BUTTERFLY VALVE COVER BRACKET



Notice Information

Ref	19796
Posted Date:	
Posted To:	General Manager / Business Owner, Technician, Parts / Accessories Coordinator, Sales Executive, Clothing Sales, Sales Manager, Aftersales Manager, Service Leader / Advisor, Accounts / Admin, Marketing Executive
Subject:	Service/Technical

TOL NOTICE (US&CA) – October 18, 2021

TOL Ref. #19796-SVC

SERVICE BULLETIN 591: EXHAUST BUTTERFLY VALVE COVER MOUNTING BRACKET

Triumph has released [Service Bulletin 591](#). Dealers are requested to install a replacement exhaust valve cover mounting bracket as described in the procedure outlined in the bulletin.

SB 591: Exhaust Butterfly Valve Cover Mounting Bracket				
Bulletin #	Models Affected	VIN Range		Markets
591	Speed Triple 1200 RS	From AD2117	To AU6999	All Markets

Some affected motorcycles listed in the VIN range will have been modified and repaired by Triumph prior to their release from the factory. Unmodified motorcycles can be identified by checking the 'VIN Enquiry' on www.triumphonline.net. **Motorcycles in the affected VIN range must be modified prior to delivery to the customer, or at the next dealership visit.**

Consult **Triumph Online (TOL) / Service Bulletin Page** (Bulletin # 591) or the attached [Service Bulletin 591](#) PDF for additional information including Fitting, Warranty Claim and Part Ordering instructions if applicable. Please also ensure that all relevant staff are up to date on these service instructions.

Reminder: Use the **"VIN Enquiry"** function within TOL (found under the **Service / Technical** drop-down menu) to search for any outstanding bulletins or recalls whenever a new motorcycle arrives, or a Triumph owner visits your dealership.

If you have any additional questions, please contact Triumph Customer Support at (888) 284-6288.