

2022 Plateau

1. The far lower left galley cabinet door opens when it is locked. The latch is not securing into the catch. Auth request to R&I catch, add washers for support, and reinstall. Tech asking for .20 hrs. 0.20 approved.

2021 Plateau

CABINET ON REAR DRIVER SIDE WILL NOT OPEN. LOCK HAS INTERNAL FAILURE. REMOVED LOCK AND STILL GETS STUCK. NEED TO ORDER AND REPLACE LOCK. (0.6) 0.20 approved. We will send a new push lock under warranty. Please so do NOT order.

2022 Rekon

complaint: latch on cabinet door under sink not engaging
cause: latch out of adjustment
correction: adjust latch time: .10 0.10 approved.