

2022 Tofino

p: customer states there is water leaking from the rh pillar post and the dome light over the cockpit area. is always parked level.
popped the tent up and there were no signs of water there
c: sealants poorly done
r: inspected marker lights sealed one but there is a panel on the roof near the tent that was not sealed well and appear to be the source. took it off and the primary sealant was falling apart. cleaned and applied new butyl sealant and installed, sealed with a secondary sealant. let dry and sit in the rain. watched for 2 days and drove around no evidence of leak.
labor 2.2 ~~hrs~~

The total time approved is 1.2 hours and the Authorization# 07102101 J for the work. See comments below in yellow:

inspected marker lights sealed one 0.2 approved
panel on the roof primary sealant was falling apart 1.0 approved.