

2021 Ascent

Complaint: Customer states the touch panel on mounted inside the entry door fell off when driving, causing damage to the screen, and wires pulled out of the plug.

Cause: Mounting tab on the frame is stuck in causing it not to secure

Correction: Replace touch panel.

Labor: .5 **0.50 approved. We will send you a new panel under warranty. Please do NOT order the part.**