

2022 Tofino

2. GREY TANK FULL READING EMPTY, unplugged camper, shut battery and key waited 5 minutes and filled tank again with same results. Called spyder control. Checked wires per spyder and they sent new sensor (labor 0.70) 0.70 approved.