



## SIB 13 07 21 LOUD / NOISY FUEL PUMP

BMW Motorrad  
**MODEL**

Model	Model Description	Production Date
K34	R18 / R18 Classic	To January 25, 2021

### SITUATION

Customer may complain of a noisy fuel pump. The drive frequency of the fuel pump may cause a resonance.

### PROCEDURE

In case of a customer complaint, check the I-level and update to 20-11-510 or higher if necessary.

The updated I-level changes the frequency of the fuel pump control and reduces the noise.

### WARRANTY INFORMATION

Covered under the terms of the BMW New Vehicle Limited Warranty for Motorcycles.

#### Defect code

13 61 53 02 00	DME / BMS / Motronik control unit Software bug / internal device fault
----------------	--

#### Labor Operation

61 00 002	Testing software	3 FRU
+61 00 502	Testing software	2 FRU
61 00 510	Programming control units of vehicle (along with testing software)	2 FRU

FRUs includes all repair procedures to complete the task with allowance for necessary ancillary tasks (e.g., visual inspection, lubrication, cleaning parts etc.) and administrative tasks.

Labor operation code 61 00 002 is a Main labor operation. If you are using a Main labor code for another repair, use the Plus code labor operation instead.

### QUESTIONS REGARDING THIS BULLETIN

Technical inquiries	Contact the BMW Technical Support Group via TSARA
Warranty inquiries	Submit an IDS ticket to the Warranty Department
Parts inquiries	Submit an IDS ticket to the Motorrad Parts Department

#### Supporting Materials

[picture\\_as\\_pdf 13 07 21 Loud Noisy Fuel Pump.pdf](#)

# Service Information Bulletin

Fuel Preparation and Control

September 14, 2021

13 07 21

## LOUD / NOISY FUEL PUMP



### MODEL

Model	Model Description	Production Date
K34	R18 / R18 Classic	To January 25, 2021

### SITUATION

Customer may complain of a noisy fuel pump. The drive frequency of the fuel pump may cause a resonance.

### PROCEDURE

In case of a customer complaint, check the I-level and update to 20-11-510 or higher if necessary.

The updated I-level changes the frequency of the fuel pump control and reduces the noise.

### WARRANTY INFORMATION

Covered under the terms of the BMW New Vehicle Limited Warranty for Motorcycles.

#### **Defect code**

13 61 53 02 00	DME / BMS / Motronik control unit Software bug / internal device fault
----------------	--

#### **Labor Operation**

61 00 002	Testing software	3 FRU
+61 00 502	Testing software	2 FRU
61 00 510	Programming control units of vehicle (along with testing software)	2 FRU

FRUs includes all repair procedures to complete the task with allowance for necessary ancillary tasks (e.g., visual inspection, lubrication, cleaning parts etc.) and administrative tasks.

Labor operation code 61 00 002 is a Main labor operation. If you are using a Main labor code for another repair, use the Plus code labor operation instead.

### QUESTIONS REGARDING THIS BULLETIN

Technical inquiries	Contact the BMW Technical Support Group via TSARA
Warranty inquiries	Submit an IDS ticket to the Warranty Department
Parts inquiries	Submit an IDS ticket to the Motorrad Parts Department