

**PANORAMIC ROOF PANEL BLIND INOPERATIVE, BUCKLED AND/OR STUCK****TSB 16-0036****FORD:**

2014-2016 Transit Connect

**ISSUE**

Some 2014-2016 Transit Connect vehicles may exhibit a condition in which the panoramic roof panel blind moves and stops 150 mm (6 inches) from the full open position or does not move at all. The blind may be buckled and/or stuck.

**ACTION**

Follow the Service Procedure steps to correct the condition.

**SERVICE PROCEDURE**

1. Is the panoramic roof panel blind inoperative, buckled and/or stuck?
  - a. Yes - proceed to Step 2.
  - b. No - this article does not apply. Refer to Workshop Manual (WSM), Section 501-05 for normal diagnosis.
2. Replace the panoramic roof panel blind assembly. Refer to WSM, Section 501-05.

PART NUMBER	PART NAME
DT1Z-17519A02-AB	Panoramic Roof Panel Blind Assembly

OPERATION	DESCRIPTION	TIME
160036A	2014-2016 Transit Connect Short Wheel Base: Inspect And Replace The Panoramic Roof Panel Blind Assembly (Do Not Use With Any Other Labor Operations)	3.7 Hrs.
160036B	2014-2016 Transit Connect Long Wheel Base: Inspect And Replace The Panoramic Roof Panel Blind Assembly (Do Not Use With Any Other Labor Operations)	3.9 Hrs.

**WARRANTY STATUS:**

Eligible Under Provisions Of New Vehicle Limited Warranty Coverage

Warranty/ESP coverage limits/policies/prior approvals are not altered by a TSB. Warranty/ESP coverage limits are determined by the identified causal part and verified using the OASIS part coverage tool.

**DEALER CODING**

BASIC PART NO.	CONDITION CODE
17519A02	02

NOTE: The information contained in Technical Service Bulletins is intended for use by trained, professional technicians with the knowledge, tools, and equipment to do the job properly and safely. It informs these technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by "do-it-yourselfers". Do not assume that a condition described affects your car or truck. Contact a Ford, Lincoln, or Mercury dealership to determine whether the bulletin applies to your vehicle. Warranty Policy and Extended Service Plan documentation determine Warranty and/or Extended Service Plan coverage unless stated otherwise in the TSB article. The information in this Technical Service Bulletin (TSB) was current at the time of printing. Ford Motor Company reserves the right to supersede this information with updates. The most recent information is available through Ford Motor Company's on-line technical resources.