

Service Bulletin

TECHNICAL

Subject: Air Conditioning (A/C) Blows Warm Air

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
Dranu.	woder.	from	to	from	to		
Buick	Enclave						
Cadillac	XT5	2018	2018	Sept. 1, 2017	June 1, 2018		
Chevrolet	Traverse						
GMC	Acadia						

Involved Region or Country	North America, Europe, Russia, Middle East, Israel, Japan, South Korea, South America and Africa		
Condition	Some customers may comment that the A/C blows warm air.		
Condition	The technician may find low or empty refrigerant in the system.		
Cause	This condition may be caused by a leak at the A/C condenser receiver/dehydrator tank plug.		
Correction			

Service Procedure

Important: Apply a light coating of AC oil to the O rings prior to installing the assembly. Refer to *Receiver and Dehydrator Replacement* in SI.

Parts Information

Causal Part	Description	Header	Part Number	Qty
x	RECEIVER & DEHYDRATOR KIT, A/C	Enclave	23350130	- 1
		Traverse	23350150	
		Acadia	84473270	
		XT5	04473270	

Warranty Information

For vehicles repaired under warranty, use:

Labor Operation	Description	Labor Time
4416110	Receiver and Dehydrator Replacement	Use Published Labor Operation Time

Version	3
Modified	Released October 17, 2018
Moumea	Revised June 17, 2019 - Added a Note on Clarity in the Corrections section. Revised August 20, 2021 - Removed Important statement in the Correction section.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION