

**SIB 46 02 07**

F 800 ST - Incorrect bolts to license plate bracket - Bulletin 46 002 07 (005)

2021-11-30

This Service Information Bulletin replaces SI 46 002 07 (005) **dated March 2007**.

The contents of this bulletin have not changed; bulletin numbering was updated.

**MODEL**

This document applies to the following Motorrad AG models: n/a

This document applies to the following Motorrad model descriptions: n/a

This document applies to the following Motorrad series: n/a

**SITUATION**

This document is applies to the following categories: Frame

Supporting Materials

[picture\\_as\\_pdf 46 002 07 \(005\) - F800 fender bolts.pdf](#)

Dealer Operation/ General Manager	Sales- Motorcycles	Sales - Used Motorcycles	Business Manager (F&I)	Service	Parts & Accessories	Administration
Date: March 2007 Bulletin #: 46 002 07 (005)		Source: BMW Motorrad USA Service and Technical				



# BMW Motorrad

## Service Information Bulletin

### \*\*Technical Campaign\*\*

**Subject:** Incorrect bolts fitted to license plate bracket

**Model:** F 800 ST (K71)

**Details:** By mistake, the incorrect bolts were fitted to secure the license plate bracket on a small group of motorcycles. The bolts used are 5 mm too long (35 mm in length). These longer bolts do not allow enough free play between the bracket and the fuel tank.


**Production Solution:** The correct length bolts are being installed.

<b>Motorcycles Affected:</b>	<b>ZR10361</b>	<b>ZR10362</b>	<b>ZR10363</b>	<b>ZR10364</b>	<b>ZR10365</b>
	<b>ZR10366</b>	<b>ZR10367</b>	<b>ZR10369</b>	<b>ZR10379</b>	

**Aftersales Solution:** Install the correct bolt, which is 30mm in length. The bolt in question is # 2 in the picture.

**Note:** This campaign will not show open on a DCS Vehicle History Inquiry.

**Upon delivery of a F 800 ST model please check the VIN against those listed above.**



**Warranty:** Covered under the terms of the New Motorcycle Limited Warranty.

**Warranty Information:** Reimbursement for this Technical Campaign will be via normal claim entry utilizing the following information:

Defect code: 46 62 06 77 00  
 FRU Code: 46 62 050 2 FRU - renewing number plate carrier  
 + 46 62 508 1 FRU - renewing number plate carrier

Part Number: 46 54 7 685 133 Qty. 2 M6x30 bolt

The following will explain the correct use of the work times.

Main Work: Use this labor operation number when the only repair performed is the listed warranty repair.  
 OR

+ Associated Work: Use this labor operation number when other repairs or services are performed along with the listed warranty repair.

Under no circumstances should both labor operation numbers be claimed. Attempts to claim both times will result in an unnecessary delay in claim processing and payment.