

Subject: Engineering Information - (for Pictures Only) – Engine Oil Filter Leak Original Filter (New Vehicle, Before First Oil Change Only)

Attention: This Engineering Information (EI) does not require the technician to call an engineer. This EI Lite is asking ONLY to submit the description of the issue and pictures using the Field Product Reporting (FPR) App (reference bulletin 02-00-89-002). Proceed with this EI ONLY if the oil leak is coming from the oil filter and is the original oil filter, AND the PIE number is listed in the Global Warranty Management / Investigate History link (GWM/IVH). If the customer does not have a concern that requires an oil filter replacement due to oil leak, or the EI does not show in GWM/IVH, disregard the EI and proceed with diagnostics found in published service information. THIS IS NOT A RECALL — refer to the latest version of Service Bulletin 04-00-89-053 for more details on the use of Engineering Information bulletins.

This EI has been revised to add 2021 and 2022 Model Years. Please discard PIE0651.

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Cadillac	XT5	2021	2022	—	—	3.6L (RPO LGX)	All
	XT6						
Chevrolet	Blazer						
	Camaro						
GMC	Acadia						

Involved Region or Country	U.S. Dealers ONLY
Condition	Important: If the customer did not bring their vehicle in for this concern, DO NOT proceed with this EI. Some customers may comment that they notice oil drops on the ground where their vehicle was parked that came from underneath the front of the vehicle (New Vehicle, before first oil change Only).
Cause	GM Engineering is attempting to determine the root cause of the above condition. Engineering has a need to gather information on vehicles PRIOR to repair that may exhibit this condition. As a result, this information will be used to "root cause" the customer's concern and develop/validate a field fix.

Correction

Oil Leak from Oil Filter to Mounting Interface

If you find a condition in which the oil filter is leaking between the oil filter body and the mounting surface around the gasket area, that leads to a warranty repair on one of the vehicles noted above, please use the Field Product Reporting (FPR) App, take pictures of the condition (details below), complete the required fields (adding **PIE0651** in the Condition field) and submit the FPR.

Instructions to install the FPR App on your phone and other detailed instructions can be found in the current version of Service Bulletin #02-00-89-002 (U.S. Dealers).

- Before removing the oil filter, take a picture of where the oil leak is coming from pointing to the area of concern.
Note: Use a pointer, colored tape, or other type of stick-on marker to indicate area of concern.
- The old oil filter will be requested back for review. Please make sure the oil filter is properly drained and give it to the parts department.

Warranty Information

If a Field Product Report is submitted, use:

Labor Operation	Description	Labor Time
4088128*	Engineering Information - (for Pictures Only) – Engine Oil Filter Leak Original Filter	0.3 hr

*This is a unique Labor Operation for bulletin use only.

Version	2
Modified	Released July 21, 2021 Revised November 19, 2021 – Revising to add 2021 and 2022 Model Years and remove 2020 Model Year.