

Model Series 167: ARTICO Seat Covers On Front Seat Torn/Cracked

Topic number	LI91.18-P-071629
Version	6
Function group	91.18 - Seat covers
Date	8/9/21
Validity	Model series 167 ARTICO man-made leather upholstery or ARTICO man-made leather upholstery/DINAMICA microfiber
Reason for change	Remedy revised

Complaint

On vehicles with "ARTICO man-made leather upholstery" or "ARTICO man-made leather upholstery / DINAMICA microfiber - black (601A)" the material of the seat side bolster can tear. Both the seat cushion cover and the backrest cover on the front seat can be affected here.

Attachments	
File	Description
example1.jpg	Example 1
	
example2.jpg	Example 2



[example3.jpg](#)



Example 3

Cause

The material may tear because the material in the side bolster is not suitable.

Remedy

Optimized seat covers are expected to be available as from 10/2021. In the interest of the customer, please do not change any seat covers at the moment.

Symptoms				
Body > Seat > Seat cover > Chafed through				
Body > Seat > Seat cover > Detaches				
Operation numbers/damage codes				
Op. no.	Operation text	Time	Damage code	Note

XENTRY TIPS

			91A0407	
			91N0407	