


**CONDITION OF CONCERN**

On certain Mazda3 vehicles, the LDWS lane may not be displayed properly in the active driving display when the language of Mazda Connect is set to Spanish.

Causal factor: Active Driving Display has outdated software



**SUBJECT VEHICLES**

Model	Subject VIN range	Subject build date range
2022MY Mazda3	JM1BP**** N1 500002 – 507259	From November 2, 2021 through December 7, 2021

The asterisk symbol “\*” can be any letter or number.

**WARRANTY CLAIM PROCESSING INFORMATION**

	Reprogramming of active driving display
Process Number	AM044A
Symptom Code	99
Damage Code	99
Part Number Main Cause	7777-SP-T45
Quantity	0
Labor Operation Number	XXT8LAFX
Labor Hours	0.3 hrs.

**REPAIR PROCEDURE**

Reprogram the Active Driving Display with the Mazda Modular Diagnostic System (M-MDS), using Mazda Diagnostic And Repair Software (MDARS).