



Mack Chassis - Model TD Only Equipped With An MP10 Mack Engine - AHI Harness Failure Related Fault Codes P249F00, P20DD13, P113413



> Internal Content

Once the AHI harness has been inspected and found to have failed internally, example as seen in the picture [here](#) , it will need to be replaced.



Tags

[p1134-13](#)

[p249f-00](#)

[p113413](#)

[p249f00](#)

[mack](#)

Related links and attachments

No links or attachments available



Feedback

[Give feedback](#)

to help improve the content of this article

