

44-036 - Revised Primary Engine Fuel Filter Service Process - 348/PX-9

12/16/2021

 [Edit](#)  [Clone](#)

44-036

Section

Fuel - 44

Subject

Revised Primary Engine Fuel Filter Service Process - 348/PX-9

Whats New Abstract

An improved procedure has been developed for servicing the fuel filter on model 348 chassis equipped with a PX-9 and 11 5/8" frame rails.

Condition

The initial fuel filter service procedure for model 348 chassis has been improved and it is no longer necessary to remove the fuel filter housing from the engine.

Chassis Affected

Model 348 chassis equipped with a PX-9 engine and 11 5/8" frame rails.

Action

Information Only

No action required. See Procedure section for more information.

Parts

No Parts Necessary.

Procedure

Please follow your dealership's safety procedures and precautions to ensure the vehicle can be safely repaired and maintained.

See Links section below.

Attachments

[Revised Fuel Filter Service Process](#)