



Bendix Blindspotter - Side Object Detection System - Blind Spot Sensor False Warning Information



> Internal Content

Reports show that after diagnosing the Bendix " Blindspotter " - Side Object Detection System - the blind spot sensor circuit wiring may have been chafed at the wire clamp locations shown [here](#).



Tags

k44011950

bendix

blindspotter

mack

Related links and attachments


[Blind spot sensor.pdf 3 7 2016](#)



Feedback

[Give feedback](#)

to help improve the content of this article



Wires rubbed under the clamp

