



Volvo Chassis - Models VNL, VNX Only Equipped With A USD16 Volvo Engine - AHI Harness Failure Related Fault Codes P249F00, P20DD13, P113413




> Internal Content

Once the AHI harness has been inspected and found to have failed internally, example as seen in the picture below, it will need to be replaced.



Live UI

 Tags[p113000](#)[p249f00](#)[k72182344](#)[p1130](#)[p1130-00](#)[p249f-00](#)[volvo](#)

Related links and attachments

No links or attachments available



Feedback

[Give feedback](#)

to help improve the content of this article