


# TECHNICAL TOPICS

## BODY/CHASSIS



Road Noise or Water Ingress Into Luggage Compartment	21 - 22MY XF
<p><u>Customer Voice:</u></p> <ul style="list-style-type: none"><li>- A customer may report excessive road noise while driving or water ingress into the right/ hand rear luggage compartment.</li></ul> <p><u>Technical Description:</u></p> <ul style="list-style-type: none"><li>- This may be caused by a R/H rear quarter vent panel that was not installed correctly.</li></ul> <p><u>Status:</u></p> <ul style="list-style-type: none"><li>- SSM 75623 has been published to aid in diagnosing this concern.</li><li>- Should the rear quarter vent panel be incorrectly installed, the vent panel should be replaced with a new part and installed correctly.</li></ul>	 <p>24-2016 FW00025</p>

