



Vehicle Electronic Control Unit (VECU) Fault Code MID 144 PID 383 FMI 14 (Special Instructions) Being Generated In The Cluster Display



> Internal Content

On a chassis generating a VECU fault code MID 144 PID 383 FMI 14 (Special Instructions) in the cluster display refer to the following information:

1. Check and confirm that parameter QIN is NOT ENABLED
2. It's value should be set to " 0 " (Zero) to disable.
3. Once confirmed that parameter QIN is set correctly the fault code should no longer be generated.

Tags

- [volvo](#)
- [mack](#)
- [k70499113](#)
- [mid 144 vecu](#)
- [mid 144 pid 383 fmi 14](#)

Related links and attachments

No links or attachments available

Feedback

[Give feedback](#)

to help improve the content of this article

Live UI