



SERVICE BULLETIN

Classification: BT20-015A	Reference: NTB20-076A	Date: November 18, 2021
------------------------------	--------------------------	----------------------------

NO ENGINE COVER

This bulletin has been amended. See **AMENDMENT HISTORY** below.
Please discard previous versions of this bulletin.

APPLIED VEHICLES: 2021-2022 Altima (L34)
APPLIED ENGINE: PR25DD

SERVICE INFORMATION

The APPLIED VEHICLE is not equipped with an engine cover.

DO NOT file a warranty claim for a missing engine cover.

AMENDMENT HISTORY

PUBLISHED DATE	REFERENCE	DESCRIPTION
October 30, 2020	NTB20-076	Original bulletin published
November 18, 2021	NTB20-076A	APPLIED VEHICLES revised

Nissan Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. **NOTE:** If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Nissan dealer to determine if this applies to your vehicle.