

2022 Tofino

Job 2: CO alarm will not stop chirping. No LP or CO detected, Found CO/LP detector faulty. R&R CO detector. - 0.5 HR 0.3 hour approved.