

2021 Plateau

Job line 1 – Requested Time 1.5 **1.50 approved.**

Concern: Dealer States that after replacing the LP gauge sensor that Pleasure Way suggested after multiple tests the LP level on the monitor panel still only reads between 0 and 9 percent.

Cause: Found the G-12 module has failed and needs replaced.

Correction: Talked to Spyder Controls and ran several tests on the system. Spyder said the G-12 module needs replaced. Receive G-12 module board. Remove old board. Install new board and test operation.