

2021 Tofino

Job Line 1 – Requested Time 0.5 0.50 approved. Please follow torque specification below.

Must be assembled with red loctite and torqued to not more than 8-10 lb-ft

Concern: Customer States the hinge came loose on the driver's side rear roof pop up top.

Cause: Found the flex hex bolt came loose and was lost along with the nylon washer and nylock nut.

Correction: Install new flex hex bolt, nylon washer and nylock bolt in hinge. Test pop up top operation.