

Technical Journal

TITLE:

DTC SRS-B15381B High Voltage battery loop control

REF NO: TJ 35754.5.0	ISSUING DEPARTMENT: Technical Service	CAR MARKET: United States and Canada	
PARTNER: 3 US 7515		ISSUE DATE: 2021-12-22	STATUS DATE: 2021-12-22
FUNC GROUP: 3979	FUNC DESC: miscellaneous	Page 1 of 2	

Attachment

Rows beginning with * are modified

Note! If using a printed copy of this Technical Journal, first check for the latest online version.

DESCRIPTION:

* This TJ is rewritten in its entirety

* The issue with TCAM reload is now resolved. If replacing a TCAM, perform a TCAM RELOAD according to standard VIDA procedures.

TCAM = Telematics and Connectivity Antenna Module

CSC Customer Symptom Codes

Code	Description
1Z	Service/repair/Software update failed
6O	Mobile applications Polestar Connect/Communication problems
6K	Mobile applications Volvo On Call/Activation problems
6P	Polestar Connect/Does not work
1C	Service/repair/Administrative and Factory scheduled maintenance
2V	Technician information/Software/Vehicle communication/Not for warranty use

Technical Journal 35754.5.0

DTC Diagnostic Trouble Codes

Vehicle Type

Type	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
534							2021-9999		-	202007-999952

SERVICE:

*If replacing a TCAM, perform a TCAM RELOAD according to VIDA

VST Operation Number

VST Operation Number	Description
39744-2	Control Module, Remote communication, replace

VEHICLE REPORT:

Yes, please contact Polestar Technical Support if the service solution described in this TJ has no effect.

Information to NSC:

The new TCAM SW is released now. Previous special routine is no longer needed.