

Technical Journal

TITLE:

Info request, door sealing strip coming loose

REF NO: TJ 34071.3.0	ISSUING DEPARTMENT: Technical Service	CAR MARKET: United States and Canada	
PARTNER: 3 US 7510 Volvo Car USA		ISSUE DATE: 2021-11-24	STATUS DATE: 2021-11-30
FUNC GROUP: 8451	FUNC DESC: Sealing moulding for side door	Page 1 of 3	

“Right first time in Time”

Attachment

File Name	File Size
TJ34071.jpg	0.1326 MB

Rows beginning with * are modified

Note! If using a printed copy of this Technical Journal, first check for the latest online version.

DESCRIPTION:

*Note only concerns XC40 (536)

If front or rear door mounted sealing strip coming loose, please submit a Vehicle Report for information with detailed photos showing the failure (overview + close-up). Include which door that is affected and the failure area, see attachment.

CSC Customer Symptom Codes

Code	Description
M3	Exterior trim/components/Moldings, trim loose
ZP	Sealings doors, windows, lids/Loose, poor fit, warped
R1	Doors/Water leakage/Front side door
R2	Doors/Water leakage/Rear side door

DTC Diagnostic Trouble Codes

Technical Journal 34071.3.0

Vehicle Type

Type	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
536							2020-2020	19	0220421-0999999	202035-209952
536							2020-2099	19	0220421-0999999	201935-209952
536							2020-2099	22	0220429-9999999	201935-209952

SERVICE:

Replace the sealing strip according to VIDA.


VST Operation Number

VST Operation Number	Description
84532-2	Weatherstrip side door front replace
84533-2	Weatherstrip side door rear replace

VEHICLE REPORT:

Yes, please submit a Vehicle Report with detailed photos showing the failure. Add the nr of the failure area and what door that is affected according to attachment. Use concern area "Vehicle Report" and sub concern area "Support not needed", use function group 8451.

To view TJ attachment continue to next page. This TJ has one attachment.



TJ 34071