



**NUMBER:** 23-042-15

**GROUP:** Body

**DATE:** November 07, 2015

*This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.*

**THIS SERVICE BULLETIN IS ALSO BEING RELEASED AS RAPID RESPONSE TRANSMITTAL (RRT) 15-108. ALL APPLICABLE SOLD AND UN-SOLD RRT VIN'S HAVE BEEN LOADED. TO VERIFY THAT THIS RRT SERVICE ACTION IS APPLICABLE TO THE VEHICLE, USE VIP OR PERFORM A VIN SEARCH IN TECHCONNECT. ALL REPAIRS ARE REIMBURSABLE WITHIN THE PROVISIONS OF WARRANTY.**

**SUBJECT:**

Water Entering At Door Handle Cable Grommet

**OVERVIEW:**

This bulletin involves replacing the door latch cable assembly.

**MODELS:**

2015 (BU) Jeep Renegade

**NOTE: This bulletin applies to vehicles within the following markets/countries:  
NAFTA**

**NOTE: This bulletin applies to vehicles built on or before February 24, 2015 (MDH 0224XX).**

**SYMPTOM/CONDITION:**

The outside door handle cable grommet does not seal effectively for water.

**DIAGNOSIS:**

If a customer's VIN is listed in VIP or your RRT VIN list, perform the Repair Procedure.

**PARTS REQUIRED:**

Qty.	Part No.	Description
1	68268739AA	CABLE, Release Assembly, Front Door, Right
1	68268761AA	CABLE, Release Assembly, Front Door, Left
1	68268740AA	CABLE, Release Assembly, Rear Door, Right
1	68268762AA	CABLE, Release Assembly, Rear Door, Left

**REPAIR PROCEDURE:**

Replace the door latch cable assemblies on all four doors. Refer to the detailed service procedures available in DealerCONNECT> TechCONNECT under: Service Info> 23 - Body> Door - Front> LATCH, Door> Removal/Installation and 23 - Body> Doors - Rear> DOOR, Rear> Disassembly/Assembly.

**POLICY:**

Reimbursable within the provisions of the warranty.

**TIME ALLOWANCE:**

Labor Operation No:	Description	Skill Category	Amount
23-41-01-9K	Replace Door Latch Cable Assemblies On All Four Doors (1 - Semi-Skilled)	6 - Electrical and Body Systems	2.4 Hrs.

**FAILURE CODE:**

ZZ	Service Action
----	----------------