



STAR ONLINE PUBLICATION



Case Number: S2108000154

Release Date: June 2021

Symptom/Vehicle Issue: Cluster Sets Erroneous Stored DTC's After Removing The Vehicle From Shipping/Logistics Mode And Entering Customer Mode

Technician Observation: After removing the vehicle from logistics mode the vehicles (IPC) instrument panel cluster (IPC) may set stored DTC's U0158-00-Lost Communication With Head Up Display (HUD) Module, B156D-00- Low Voltage Differential Signal (LVDS) Video Cable.

Discussion: During vehicle prep and or removal of the vehicle from logistics mode, the IPC may set stored codes U0158, B156D-00. These codes do not have a component and or customer impact. Do not replace any components for the above DTC's, clear the faults to repair.

This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

Contact STAR Center, or your Technical Assistance Center Via TechCONNECT or eCONTACT ticket if no solution is found