



**NUMBER:** 23-028-21

**GROUP:** 23 - Body

**DATE:** August 25, 2021

*This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.*

**SUBJECT:**

Water Leak At CHMSL

**OVERVIEW:**

This bulletin involves replacing the Center High Mounted Stop Lamp (CHMSL) assembly.

**MODELS:**

2019 - 2021 (DT) RAM 1500 Pickup

**NOTE:** This bulletin applies to vehicles within the following markets/countries: North America, EMEA and LATAM.

**NOTE:** This bulletin applies to vehicles built on or before October 01, 2020 (MDH 1001XX) with Cargo And CHMSL Lamp (Sales Code LPE).

**SYMPTOM/CONDITION:**

The customer may experience on one or more of the following:

- Water on the headliner.
- Water at the back of the cab.
- A leak from the third brake light/CHMSL.

**DIAGNOSIS:**

If the customer describes the symptom/condition listed above, perform the Repair Procedure.

**PARTS REQUIRED:**

Qty.	Part No.	Description
1 (A/R)	68298380AG	Lamp, Center High Mounted Stop

**REPAIR PROCEDURE:**

1. Replace the CHMSL assembly. Refer to the detailed service procedures available in DealerCONNECT> Service Library under: Service Info>08 - Electrical / 8L - Lamps and Lighting / Lamps/Lighting - Exterior / Lamp, Center High Mounted Stop / Removal and Installation.

**NOTE: Ensure interior is dry before returning the vehicle to the customer.**

**POLICY:**

Reimbursable within the provisions of the warranty.

**TIME ALLOWANCE:**

Labor Operation No:	Description	Skill Category	Amount
08-50-88-93	Lamp, Center High Mounted Stop - Replace (0 - Introduction)	6 - Electrical and Body Systems	0.3 Hrs.

**FAILURE CODE:**

ZZ	Service Action
----	----------------