
WML0 Stop Delivery – Retrofitting loudspeaker booster



WML0 Stop Delivery - Retrofitting loudspeaker booster

Update 12/3/21

Please be advised that parts have begun to be allocated for small quantities of vehicles affected by WML0 in dealer inventory. Please continue to refrain from ordering parts or requests regarding the availability of parts.

Repairs can now begin on affected vehicles with an allocated part.

The TI for WML0 has been published and is available in PCSS and in the AfterSales Document Database

Vehicle blocking

Vehicles must not be delivered to customers until the required remedial measure has been carried out. Therefore, please carry out following Stop Delivery, immediately.

Important Information:

- A VIN list is attached to this post and will be updated weekly
- At present, no statement can be made about the availability of parts. Together with our suppliers, we
 are working at high priority to procure the required capacities of components. As soon as these are
 available, we will inform you immediately. In the meantime, please refrain from requests regarding the
 availability of parts.
- The Technical Information is now available and repairs can now begin (as of 12/3)
- The creation of PCSS jobs as well as the invoicing of the campaign is only possible with the availability of the remedial measure.

Overview

Due to worldwide semiconductor shortages experienced by some suppliers, the affected vehicles were built without a loudspeaker booster.

As a result, audio output is not available on these vehicles.

For this reason, the loudspeaker booster must be retrofitted on the affected vehicles before handing the vehicles over to customers once the control unit is available.

Model type	Macan (95B)Cayenne (9YA/9YB)
Model year	2021-2022
Vehicle specifications	BOSE Surround Sound System (M-No. 9VL)
Number of affected vehicles	TBD*

*Please note due to newly produced vehicles from current production, more vehicles will be assigned to this campaign until loudspeaker boosters are available.

Vehicle usage

The vehicles may only be driven for loading and unloading purposes in the transport chain and, if necessary, by dealer personnel only.

A further use is not permitted. Test drives are to be omitted.

Instructions and remedial measures

The remedial measure is now available from 12/3. The TI is available from 12/3 in PCSS and the AfterSales Document Database