## **GPOP - Issue Review System**

**Part Number:** 68462119A\$

Part Description: COMPRESSOR ASSEMBLY, Air Suspension, Module

**Issue** ASCM replacement is rarely necessary. If the DTC is stored and able to be cleared, **Description:** component replacement is not necessary.

Please follow the service procedures to attempt to clear any active fault(s) which includes module hard reset, full CAN power down/sleep, or DTC clear in WiTech.

Please contact FCA Redacted Content prior to any ASCM replacement at FCA Redacted Content

If no response within 15 minutes, please proceed with repair.

Any new module requires a flash following installation regardless of whether the current part number is up-to-date .