



# SAFETY RECALL W09 DRIVER AIR BAG EMBLEM

## Updated Dealer Instructions

FEBRUARY 2021

As of 2/4/2021 the Dealer Instructions for Safety Recall W09 have been updated to include the final remedy. The Driver Air Bag (DAB) must be disassembled and emblem retainers inspected to determine if all the emblem retainers are securely attached. If the emblem retainers are securely attached a tape package will be required to remedy the vehicle. If any emblem retainers are detached or the emblem is missing, the emblem and the emblem retainers will be removed from the DAB. Vehicles that have had the emblem removed will have the W09 Safety Recall marked completed upon payment of the warranty claim and then the vehicle will be included in a future Customer Satisfaction Notification (CSN) that will cover having their DAB cover and emblem replaced. Customers will receive a notification in the mail once these parts become available.

