



STAR ONLINE PUBLICATION



Case Number: S2108000064

Release Date: 3/9/2021

Symptom/Vehicle Issue: Appearance Of A Coolant Leak On The Power Pack Unit (PPU) Fitting Due To Assembly Lubricant

Discussion: Upon examining the PPU or underside of the vehicle, you may discover the appearance of a green discharge at the PPU coolant fitting. The green substance is often associated with Coolant, but is actually lubricant used in the assembly of the PPU. This is normal and does not indicate a leak. **The PPU or any of its associated coolant lines SHOULD NOT BE REPLACED for this condition.**



Green Assembly Lubricant On PPU Coolant Fitting

This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

Contact STAR Center, or your Technical Assistance Center Via TechCONNECT or eCONTACT ticket if no solution is found