



STAR ONLINE PUBLICATION

Case Number: S1923000015 Rev A

Release Date: 03/31/2021

Symptom/Vehicle Issue: Transmission Column Shifter Lever Feels Loose

Discussion: If the transmission column shift lever is verified to have looseness replace the shifter and its fasteners- 06509081AA. Do not reuse the shifter bolts. They have thread locker applied and are 1 time use only. **NOTE** New Fastener torque is 12 Ft/Lbs or 16 NM

This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

Contact STAR Center, or your Technical Assistance Center Via TechCONNECT or eCONTACT ticket if no solution is found