GPOP - Issue Review System

Part Number: 68204485A\$, 68204484A\$

Part Description: LATCH, Storage Bin Lid (Rambox)

Issue If the Rambox storage bin lid latch is being replaced for the lid not opening or Description: latching properly, replace the latch and lid assembly with all of the sub components instead of just replacing the latch only. Do not replace the Rambox. Please ship all the replaced components to QEC.

> Please contact FCA Redacted Content or FCA Redacted Content to set up the part return to QEC.

If no response in 15 minutes, proceed with repair.

Contact Us at CAGRIS@Stellantis.com for feedback related ONLY to this GPOP Tech Tip. DO NOT email regarding repair procedures unrelated to this Tech Tip or part order inquires. Please include the Part Number (s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.