

GPOP - Issue Review System

Part Number: 6WR57DX9A\$, 6WR58DX9A\$, 6WR59DX9A\$, 04672882A\$, 04672883A\$

Part Description: CAMERA, Interior

Issue Description: Prior to replacing the ICM1 (interior camera module) due to the presence of the STORED DTC B229C-96 "Interior Camera Module - Component Internal Failure" on the 21MY RU or WL and 22MY WS vehicles, verify there are no observable issues with the FamCam feature.
If there are no observable issues with the FamCam feature, and no customer complaints related to the FamCam, clear the STORED fault and do not replace the camera. This issue is due to a temperature detection error and will be corrected in a subsequent SW release.

~ _____ ~
Contact us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. Please include the Part Number(s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.