


Case Number: S210900002

Release Date: June 2021

Symptom/Vehicle Issue: Small Occasional Oil Leak, Drip, Front Of Engine

Customer Complaint/Technician Observation: Owner complains of a small oil leak appears to be at the front area. Technician can locate what appears to be a very small leak front of vehicle, cannot pinpoint where the leak is from.

Repair Procedure: Inspect oil temperature sensor as a suspect leak location, remove and tighten to specs listed in dealer connect torque specifications for this switch. No parts required.



NOTE: This Harness Assembly is a COMPOSITE depicting all available options. Some connectors may not be present on vehicle.

This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

Contact STAR Center, or your Technical Assistance Center Via TechCONNECT or eCONTACT ticket if no solution is found

FCA US LLC