

GPOP - Issue Review System

Part Number: 68206714A\$, 68206715A\$

Part Description: TORSION ROD, Storage Bin (Rambox)

Issue Description: If the Rambox storage bin Torsion Rods are being replaced for the lid not opening issue, replace the complete Rambox Bin and Lid assembly with all of the sub components instead of just replacing the Torsion Rods only. Please ship the complete Rambox Bin and Lid assembly without dis-assembling the lid or hinges to QEC.

Please contact FCA Redacted Content to set up the part return to QEC.

If no response in 15 minutes, proceed with repair.

~____~
Contact Us at CAGRIS@Stellantis.com for feedback related ONLY to this GPOP Tech Tip. DO NOT email regarding repair procedures unrelated to this Tech Tip or part order inquires. Please include the Part Number (s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.
