



## STAR ONLINE PUBLICATION



**Case Number:** S2108000091

**Release Date:** May 2021

**Symptom/Vehicle Issue:** When The PTO Is Engaged, Engine RPM Will Not Exceed 1100 RPM And The Engine Surges. Diagnostic Trouble Codes (DTCs) P061B – Internal Control Module Torque Performance, And/Or P064B – PTO Control Module, Set.

**Discussion:** A small number of customers may experience issues with PTO operation. These issues include:

- Engine RPM will not exceed 1100 RPM with the PTO engaged
- Engine RPM surging with the PTO engaged
- PTO shuts down with DTC P061B and/or P064B setting.

If you have a vehicle with one of the issues listed above, be sure to perform all published diagnostics for the specific condition. Verify that the PTO system installed is installed properly, and is properly programmed per the customer's preferences. Also verify the PCM is at the latest available calibration.

If no issues are found, the issue may be related to software. Engineering is currently investigating potential software updates, in addition to those already released, to address these conditions.

This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

**Contact STAR Center, or your Technical Assistance Center Via TechCONNECT or eCONTACT ticket if no solution is found**