



## STAR ONLINE PUBLICATION



**Case Number:** S2108000166

**Release Date:** July 2021

**Symptom/Vehicle Issue:** Seat Belt Chime And/Or Turn Signal Indicator Sound Inoperative

**Discussion:** The seat belt reminder light may illuminate but no chime is heard. When selecting either the left or right turn signal indicator. The turn signal lamp may illuminate but no sound is heard.

**Diagnosis:** Start the vehicle and wait 1 minute. Open the Drivers door. The seat belt reminder light should illuminate and the chime should be heard.

Actuate either the left or right turn signals. The corresponding turn signal lamp indicator should illuminate and the turn signal sound should be heard.

If either the seat belt chime and/or turn signal sounds is not heard perform the repair procedure below. For this SOL to be applicable all other functions of the IPC should other than the indicator sounds should work. If other functions of the IPC do not operate, further diagnostics should be performed.

**Repair:** Replace the Instrument Cluster with the latest available part number.

**Verification:** Once the IPC has been replaced, confirm that the chime and indicator sounds are heard.

This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

**Contact STAR Center, or your Technical Assistance Center Via TechCONNECT or eCONTACT ticket if no solution is found**