



GENESIS

Technical Service Bulletin

GROUP Campaign	NUMBER 21-01-077G
DATE DECEMBER 2021	MODEL(S) G90 (HI) G70 (IK)

SUBJECT: FUEL CAP INSPECTION AND REPLACEMENT
(SERVICE CAMPAIGN T21G)

★ IMPORTANT


*****Dealer Stock and Retail Vehicles*****

Dealers must perform this Campaign on all affected vehicles prior to customer retail delivery and whenever an affected vehicle is in the shop for any maintenance or repair.

When a vehicle arrives at the Service Department, access Hyundai Motor America's "Vehicle Information Screen (VIS)" via WEBDCS to identify open Campaigns.

Applicable Vehicles:
 Certain 2022MY G90 (HI) vehicles produced between 07/13/2021~09/06/2021.
 Certain 2022MY G70 (IK) vehicles produced between 07/13/2021~09/11/2021.

Parts Information:

Parts Name	Part Number	Figure
Fuel Cap	31010-3L600	

Warranty Information:

Model	Op. Code	Operation	Op. Time	Causal Part	Nature Code	Cause Code
G90 (HI)	10D209R2	FUEL CAP INSPECTION	0.2 M/H	31010-3L600	I11	ZZ3
G70 (IK)						
G90 (HI)	10D209R3	FUEL CAP INSPECTION AND REPLACEMENT	0.3 M/H			
G70 (IK)						

NOTE 1: Submit claim on Campaign Claim Entry Screen.

NOTE 2: If a part that is not covered by this campaign is in need of replacement while performing this campaign and the affected part is still under warranty, submit a separate claim using the same Repair Order. If the affected part is out of warranty, submit a Prior Approval Request for goodwill consideration prior to performing the work.

Service Procedure:

- Open the fuel door and completely rotate the cap clockwise to verify the fuel cap clicks into place.
 - If there is no click, replace the fuel cap.

If there is a click, no further action is necessary.



- The service procedure is complete.