

[Next Unread Message](#)**View Message**

Sent on	01	04	2022	Expires on	01	17	2022
From	Technical Information & Support Group						
Subject	Request for Info: 2020-2022 RDX & 2022 MDX Sunroof Seal Deformation						

PRIORITY/ACTION REQUIRED

To: All Acura Service Managers/Consultants
 From: Technical Information & Support Group
 RE: Request for Info: 2020-2022 RDX & 2022 MDX Sunroof Seal Deformation

**This message is solely directed to Acura dealership personnel; please handle accordingly.
 Print this iN message and provide a copy to the Shop Foreman and all Service Consultants.**

Background

American Honda Motor Co., Inc. (AHM) is searching for certain 2020-2022 RDXs & 2022 MDXs with a client complaint of deformed or damaged sunroof seals. To better understand the cause of this condition, AHM would like to obtain images of the sunroof seal prior to you attempting a repair of any kind.

Qualifiers

AHM is interested ONLY if the vehicle meets the following requirements:

1. Must be able to visually confirm the issue.
2. No repair has been attempted including the removal of the sunroof assembly.

Action Required

If a vehicle matching the qualifiers above comes into your dealership, please e-mail Technical Information & Support (TIS - formerly TRS) at tis@ahm.honda.com. TIS will contact you to record certain vehicle information and provide you with further instructions.

Please be sure to include the following information in your e-mail.

E-mail Title:

1. Model Year (e.g. 2020)
2. Model Name (e.g. TLX)
3. Issue (e.g. Brake Judder)
4. VIN

E-Mail Body:

1. Dealer Number
2. Your Name
3. Best Phone Number to be Reached
4. Current Mileage

Thank you.