

**On-car analysis list from January 18th, 2022  
please contact VW Helpline before attempting repair**

	<b>Models</b>	<b>MY</b>	<b>Engine</b>	<b>Transmission</b>	<b>Topic</b>	<b>Customer Complaint</b>
<b>Powertrain</b>	Atlas, Atlas Cross Sport	20-21	3.6L (CDVC)	All	MIL-on P0087 P0148 P053F	Customer states MIL-on with P0087 P053F in the ECM <b>(Untouched vehicles)</b>
	Atlas, Atlas Cross Sport	21	All	All	Heat Shield Rattle	Customer states rattle noise from the underbody heat shields
	ID.4	21	All	All	POCFF and/or P2B28 (12/13/2021)	Customer states Electrical System not Working Correctly Message with POCFF and/or P2B28 in HV Battery <b>(Only if diagnosis leads to V590 pump replacement after TB 2064967/1 has been performed)</b> <b>(Vehicle must be held untouched until coolant sample bottle is received at dealer)</b>
<b>Chassis</b>	Atlas, Atlas Cross Sport	21	All	All	Front Suspension Noise	Customer states noise from front suspension <b>(Untouched vehicles)</b> <b>Must be after VIN break MC537933 (Atlas) or MC201092 (Atlas Cross Sport)</b>
<b>Electric</b>	Tiguan	21-22	All	All	Blower stays on Faults B10AE31, B10AE04	Customer states blower stays on <b>(Must have faults code B10AE31 and/or B10AE04 and Corrosion in high pressure sensor connector)</b>
<b>Other</b>	Jetta, Golf, Beetle, SportWagen	09-14	2.0 (CJAA and CBEA)	All	TDI Inspection	Any TDI Gen I TDI within the vehicle/MY range. Topic is for <b>information gathering only</b> Web tickets only <b>(\$40 technician gift card for vehicles reported)</b> <b>(Complete worksheet Gen 1 TDI No DPF faults VIN4PIN when creating WEB ticket)</b> <b>(Cannot have any DPF faults/DPF related issues)</b>