

View Message

Sent on	01	25	2022	Expires on	02	08	2022
----------------	----	----	------	-------------------	----	----	------

From	Technical Information & Support Group
-------------	---------------------------------------

Subject	Request for Visit: 2018-2021 Accord Windshield Wiper Detached Linkage (Zone 2)
----------------	--

PRIORITY/ACTION REQUIRED

To: All Honda Service Managers/Advisors
From: Technical Information & Support Group
RE: Request for Visit: 2018-2021 Accord Windshield Wiper Detached Linkage (Zone 2)

This message is solely directed to Honda dealership personnel; please handle accordingly.
Print this iN message and provide a copy to the Shop Foreman and all Service Advisors.

Background

American Honda Motor Co., Inc. (AHM) is searching for certain 2018-2021 Accords with a customer complaint of the windshield wiper inop due to detached linkage. To better understand the cause of this condition, AHM would like to inspect the vehicle before you attempt a repair of any kind.

Qualifiers

AHM is interested ONLY if the vehicle meets the following requirement:

1. Must confirm that the wiper linkage is detached.
2. No prior repair to the wiper linkage.
3. No repair has been attempted for this issue.

Action Required

If a vehicle matching the description above comes into your dealership, please e-mail Technical Information & Support (TIS) at tis@ahm.honda.com. TIS will contact you to record certain vehicle information and provide you with further instructions.

Please be sure to include the following information in your e-mail.

E-mail Title:

1. Model Year (e.g. 2020)
2. Model Name (e.g. Accord)
3. Issue (e.g. Brake Judder)
4. VIN

E-Mail Body:

1. Dealer Number
2. Your Name
3. Best Phone Number to reach you
4. Current Mileage

Thank you.