

Technical Service Bulletin

90 Instrument cluster: various malfunction LEDs are lit sporadically without DTCs 90 22 33 2064789/2 January 7, 2022. Supersedes Technical Service Bulletin Group 90 number 21-17 dated October 13, 2021 for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
S4, and S5	2020 – 2021	All	With analog instrument cluster.
S4	2022	000001 – 008379	With analog instrument cluster.
S5	2022	N000001 - 001690 OR A000001 – 009630	With analog instrument cluster.

Condition

REVISION HISTORY				
Revision	Date	Purpose		
2	-	Revised title Revised header (Add Model Year and VIN break)		
		Revised <i>Service</i> (Removed photo-doc requirement)		
1	10/13/2021	Initial publication		

Customer states:

- Various malfunction indicator LEDs are sporadically lit in the instrument cluster while driving.
- The instrument cluster functions normally otherwise.

Workshop findings:

• No relevant DTCs are stored in the vehicle.

Technical Background

There is a hardware defect within the instrument cluster.



Technical Service Bulletin

Production Solution

Not applicable.

Service

Please replace the instrument cluster according to the instructions in the Elsa Repair Manual.

Warranty

Claim Type:	 110 up to 48 Months/50,000 Miles. G10 for CPO Covered Vehicles – Verify Owner. If the vehicle is outside any warranty, this Technical Service Bulletin is informational only. 		
Service Number:	9025		
Damage Code:	0040		
Labor Operations:	Replace the instrument cluster	9025 5500	See SRT with associated operations
Diagnostic Time:	GFF	0150 0000	Time stated on the diagnostic protocol (Max 30 TU)
	Road test prior to the service procedure	No allowance	0 TU
	Road test after the service procedure	No allowance	0 TU
Claim Comment:	As per TSB #2064789/2		



Technical Service Bulletin

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Required Parts and Tools

Always check with your Parts Department and/or ETKA for the latest information and parts bulletins.						
Part Number	Part Description	Quantity				
See ETKA	Fasteners, Bolts, Nuts, and Screws as needed per the Repair Manual	See ETKA/ELSA				
See ETKA	Instrument Cluster	01				

Additional Information

All parts and service references provided in this TSB (2065605/1) are subject to change and/or removal.

©2022 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.