

**This document is uncontrolled when printed. Before use, check the Knowledge Base within the McLaren Retailer Portal to verify that this is the current version.**

## Document Information

**Location:** Electrical/Electrical Systems

**Topic:** Instrument Cluster Behaviour Abnormal

**Condition:** Intermittent

**Diagnostic Trouble Codes:** N/A

## Measure

If a customer concern is received regarding the below concerns, please continue to update the IC software to **PF4.2 - Emerald: 31MA054CP.03/S12: 31MA057CP.03**

Examples:

- Menu selection not storing correctly. i.e. Folding mirrors set to off, but mirrors still folding when vehicle is locked
- When scrolling down through IC menus, options go from OFF to ON without user input. See video in attachments section.

## Parts Information

N/A

## Attachments

[Menu Selection Video](#)

## KA Update Information

06/01/2022 - KA Released

**This document is uncontrolled when printed. Before use, check the Knowledge Base within the McLaren Retailer Portal to verify that this is the current version.**