

# CAMPAIGN LAUNCH STATUS

## H374 and N622 - EMISSION RECALLS - FUELING ADAPPTIONS



EMISSION RECALLS – N622 and H374 SECONDARY FUELING ADAPPTIONS	
AFFECTED MODELS	18MY RR Evoque, Discovery Sport, RR Velar, Jaguar F-PACE, XF, E-PACE and XE.
VOLUME AFFECTED	Jaguar 11,652 USA. Land Rover 16,335
ISSUE/REPAIR	An Issue has been identified on certain 2018 MY vehicles with Ingenium I4 2.0L petrol engines. A Powertrain Control Module (PCM) software diagnostic monitoring routine contains a software error. Normal vehicle operation requires the Malfunction Indicator Lamp (MIL) to illuminate when the fueling adaption values are between 0.07% to 0.08% and -0.07% to -0.08% and a Diagnostic Trouble Code(s) (DTC) is set. With the software error present, the MIL will not illuminate as required. Vehicles will be corrected with a PCM software update.
REPAIR TIME	0.20 hrs + Drive In/Out
CAMPAIGN REPAIR LAUNCH TARGET	January 18 <sup>th</sup> , 2022
Notes	Customers will be notified by mail to contact Retailers to make service appointments

