SERVICE ACTION N647 - Unable To Disengage All Wheel Drive (AWD)





NAS22.01.011 WORKSHOP

CAN/USA

AFTERSALES BULLETIN JANUARY 28, 2022

# DESCRIPTION OF ISSUE

A concern has been identified with certain 2021 model year Range Rover Evoque and Discovery Sport vehicles manufactured at the Halewood UK assembly plant, where due to an issue in the Anti-Lock Brake System Control Module (ABS) software, the vehicle will not disconnect the rear driven wheels from the powertrain. The vehicle will remain in All Wheel Drive (AWD) and not de-clutch the rear wheels from the powertrain and self-select 2-wheel drive mode.

# AFFECTED VEHICLE RANGE

Range Rover Evoque (LZ)

Model Year: ..... 2021

VIN: ..... SALZA2BX8MH121899 - SALZA2BX2MH159080

Visit the British Brands Sales Suite (BBSS) website for a list of affected vehicles at your retailer.

## SERVICE PROGRAM / REWORK ACTION

An authorized Land Rover retailer will update the ECU All-Wheel Drive Module (AWD) software to the latest level. There will be no charge to owners for this action under this program.

## ACTION TO BE TAKEN

Use the Jaguar Land Rover claims submission system to make sure that the vehicle is affected by this program prior to undertaking any rework action.

Retailers are required to HOLD affected new vehicles that are within your control and refrain from releasing the vehicles for new vehicle sale pending completion of the rework action. Affected vehicles already in the hands of customers should be updated at the next available opportunity.

Refer to Technical Bulletin N647NAS, Service Action: Unable To Disengage All Wheel Drive (AWD)

## PARTS

No parts required.

## TOOLS

Refer to Technical Bulletin noted above for any required tools.

#### WARRANTY

NOTE: use the Jaguar Land Rover claims submission system to make sure that a vehicle is affected by this program prior to undertaking any rework action.

Jaguar Land Rover North America, LLC 100 Jaguar Land Rover Way Mahwah, NJ 07495 At the time of confirming a booking for vehicle repair, make sure that all outstanding Recall and Service Actions are identified to make sure the correct parts are available and adequate workshop time is allocated for repairs to be completed at one visit.

Warranty claims must be submitted quoting the Program Code N647NAS together with the relevant Option Code. The SRO and parts information is included for information only. The Option Code(s) that allows for the drive in/drive out allowance can only be claimed if the vehicle is brought back into the workshop for this action alone to be undertaken.

Repair procedures are under constant review and therefore times / prices are subject to change; those quoted here must be taken as guidance only. Use TOPIx to obtain the latest repair time.

This program is valid for a limited time only. Warranty claims must be submitted for payment within 30 calendar days of completion of the repair.

PROGRAM CODE	OPTION CODE	DESCRIPTION	SRO	TIME (HOURS)
N647	Α	AWD - Update ECU	85.41.02	0.2
N647		AWD - Update ECU Drive in/drive out	85.41.02 10.10.10	0.2 0.2

\*Normal Warranty policies and procedures apply.