

TECHNICAL TOPICS

BODY/CHASSIS



Water Ingress Into Passenger Compartment

20 - 22MY Defender

Customer Voice:

- A customer may report water ingress into the floor carpet.

Technical Description:

- This may be caused by improper sealing of the lower A-Pillar body seam. This can cause water to enter the vehicle cabin behind the floor carpet. This can also lead to water leaking down the vehicle wiring harness and into the transmission wiring connector (C31D1/2) and causing a battery draw and cooling fan to run continuously with the vehicle turned off.

Status:

- The procedure to diagnose and repair this water leak concern has been published in the Workshop Manual Section 501-25C: Body Repairs – Water Leaks > Diagnosis and Testing > Water Leak Diagnostics.

