



Exhaust Gas Recirculation (EGR) System - Fault Codes SPN 412 FMI 0,2,5; Diagnostic Trouble Codes (DTC) P040A, P040B, P1121 - Temperature Sensor Inspection



> Internal Content

If any of the relevant codes appear on a DTC Readout:

- Inspect the EGR temperature sensor connector for pin damage, dust, oxidation, or corrosion and replace the sensor as necessary.

If damage to the connector or the sensor is found:

- Replace the terminals of the EGR temperature sensor connector on the engine harness.

Tags

k86900043 p040a-13 p040b-64 p1121-00
p1121-98 spn 412 fmi 2 spn 412 fmi 5
spn 412 fmi 0 p040a13 p040b64 p112100
p112198 volvo mack

Related links and attachments

Live UI links or attachments available



Feedback

[Give feedback](#)

to help improve the content of this article